

000

NOUS41 KILN 250241

PNSILN

INZ050-058-059-066-073>075-080-KYZ089>100-OHZ026-034-035-042>046-

051>056-060>065-070>074-077>082-088-250700-

PUBLIC INFORMATION STATEMENT...UPDATED

NATIONAL WEATHER SERVICE WILMINGTON OH

940 PM EST THU DEC 24 2015

...ADDITIONAL INFORMATION FOR TORNADO CONFIRMED SOUTH OF BUTLER IN

PENDLETON COUNTY KENTUCKY...

LOCATION...SOUTH OF BUTLER IN PENDLETON COUNTY KENTUCKY

DATE...DECEMBER 23 2015

ESTIMATED TIME... 811 TO 820 PM EST

MAXIMUM EF-SCALE RATING...EF1

ESTIMATED MAXIMUM WIND SPEED...87 MPH

MAXIMUM PATH WIDTH...1/4 MILE WIDE

PATH LENGTH...3.75 MILES

* FATALITIES...0

* INJURIES...3

* THE INFORMATION IN THIS STATEMENT IS PRELIMINARY AND SUBJECT TO

CHANGE PENDING FINAL REVIEW OF THE EVENT(S) AND PUBLICATION IN

NWS STORM DATA.

...SUMMARY...

THE NATIONAL WEATHER SERVICE IN WILMINGTON OH HAS CONFIRMED A TORNADO SOUTH OF BUTLER IN PENDLETON COUNTY KENTUCKY ON DECEMBER 23 2015.

DAMAGE WAS FIRST OBSERVED FROM THIS TORNADO JUST NORTH OF THE INTERSECTION OF U.S. ROUTE 27 AND BETHEL LANE. THIS LOCATION IS SOUTH OF BUTLER AND NORTHWEST OF FALMOUTH IN PENDLETON COUNTY. A MOBILE HOME ORIGINALLY ANCHORED INTO THE GROUND AT 8-10 POINTS WAS TILTED AND BRIEFLY LIFTED BEFORE ROLLING ONTO ITS TOP ON THE EAST SIDE OF BETHEL LANE. THE TWO RESIDENTS SUSTAINED MINOR INJURIES REQUIRING OVERNIGHT HOSPITALIZATION. DEBRIS FROM THE MOBILE HOME WAS CARRIED DOWNWIND FOR APPROXIMATELY ONE-TENTH OF A MILE. THE DEBRIS FIELD REMAINED CONFINED TO A NARROW PATH AS IT TAPERED TO THE EAST-NORTHEAST. THIS SEEMED INDICATIVE OF CONVERGENT MOTION ASSOCIATED WITH THE CIRCULATION. THERE WERE ALSO SEVERAL 6-8 INCH TREES SNAPPED IMMEDIATELY WEST OF THE MOBILE HOME. THIS IS LIKELY WHERE THE FIRST TOUCHDOWN OCCURRED.

THE NEXT DAMAGE LOCATION WAS A METAL BARN ON ASHCRAFT ROAD. THE ENTIRE ROOF WAS LIFTED AND REMOVED FROM THE BARN. THE ROOF MEASURED APPROXIMATELY 60 FEET BY 30 FEET AND THE BARN WAS RELATIVELY NEW CONSTRUCTION WITHIN THE LAST 10 YEARS. THE ROOF WAS CARRIED INTO

ADJACENT TREES IMMEDIATELY NORTHEAST OF THE STRUCTURE. THERE WAS MINOR DAMAGE TO A SMALLER BARN JUST NORTHWEST OF THE PATH CENTER LINE. THE HOMEOWNER ALSO DESCRIBED A DOCK APPROXIMATELY 15 FEET SQUARE IMMEDIATELY SOUTH THAT WAS PULLED FROM ITS ANCHOR AND MOVED NORTH-NORTHEAST ACROSS A POND TOWARD THE PATH CENTER LINE. ALL OF THIS DAMAGE INDICATED A CONVERGENT AND LIFTING MOTION ASSOCIATED WITH THE TORNADO.

DAMAGE WAS NEXT OBSERVED ALONG ROUTE 609 JUST SOUTH OF THE INTERSECTION WITH DAVIS ROAD. ONE BARN WEST OF ROUTE 609 WAS DESTROYED AND A TREE APPROXIMATELY 20 INCHES IN DIAMETER IMMEDIATELY EAST OF THE ROAD WAS SNAPPED AT THE TRUNK AND FELL AGAINST A RESIDENCE. DEBRIS WAS CARRIED BETWEEN ONE AND TWO TENTHS OF A MILE TO THE NORTHEAST. ANOTHER BARN JUST TO THE NORTH WAS PARTIALLY DESTROYED. TORNADIC DAMAGE WAS NOT AS CONCLUSIVE AT THIS LOCATION... BUT DEBRIS WAS CONFINED TO A NARROW PATH LIKELY DUE TO CONVERGENT WIND MOTION.

A NUMBER OF TREES WERE SNAPPED TO THE NORTHEAST ALONG DAVIS ROAD. TREES RANGED IN DIAMETER FROM 8-16 INCHES. THE CLEAREST EVIDENCE OF CIRCULATION ON THE GROUND WAS LOCATED ALONG ROUTE 159 WHERE SEVERAL TYPES OF DAMAGE OCCURRED AT A RESIDENCE SOUTH OF THE INTERSECTION WITH DAVIS ROAD. THE ROOF WAS PARTIALLY REMOVED FROM THE RESIDENCE AND SOME OF THE INSULATION WAS DISPERSED TO THE WEST AND SPATTERED AGAINST THE WEST SIDE OF THE HOUSE. INSULATION WAS ALSO SPATTERED ON

TREES IMMEDIATELY TO THE NORTHWEST. HEAVY SECTIONS OF METAL FENCING FROM A HORSE CORRAL WERE LIFTED AND CARRIED APPROXIMATELY 50 YARDS TO THE WEST. BOTH OF THESE DEBRIS FIELDS WERE CARRIED AND DEPOSITED OPPOSITE THE STORM MOTION. A NUMBER OF TREES JUST NORTH AND SOUTH OF THE RESIDENCE WERE ALSO SNAPPED.

THE FINAL DAMAGE WAS FOUND ALONG HICKORY GROVE ROAD SOUTH OF THE INTERSECTION WITH ROUTE 10. THIS IS THE ESTIMATED END OF THE TORNADO PATH. A CAMPER WAS LIFTED TO THE NORTH-NORTHEAST APPROXIMATELY 10-15 FEET OVER TREES BEFORE BEING DROPPED AND DESTROYED. THERE WAS ALSO MINOR STRUCTURAL DAMAGE AT TWO NEARBY MOBILE HOMES. THIS DAMAGE CONSISTED OF GARAGE DOORS BLOWN INWARD AND SOME ROOF DAMAGE.

THANKS IS EXTENDED TO THE PENDLETON COUNTY EMA AND OTHER LOCAL OFFICIALS WHO ASSISTED WITH THE SURVEY. EYEWITNESS ACCOUNTS FROM THE AFFECTED HOMEOWNERS WERE ALSO GREATLY APPRECIATED.

THIS INFORMATION CAN ALSO BE FOUND ON OUR WEBSITE AT WEATHER.GOV/ILN.

FOR REFERENCE...THE ENHANCED FUJITA SCALE CLASSIFIES TORNADOES INTO THE FOLLOWING CATEGORIES:

EF0...WIND SPEEDS 65 TO 85 MPH.

EF1...WIND SPEEDS 86 TO 110 MPH.

EF2...WIND SPEEDS 111 TO 135 MPH.

EF3...WIND SPEEDS 136 TO 165 MPH.

EF4...WIND SPEEDS 166 TO 200 MPH.

EF5...WIND SPEEDS GREATER THAN 200 MPH.

\$\$

SHOBE2