

Purpose

Technique HCLTR sets the trace level for the Hydrologic Command Language routines.

Valid values are NO (0), YES (1) and other valid trace levels.

The Global default is NO (0).

This Technique is Universal.

Form of Input

HCLTR(integer)

where integer is the trace level

Example

HCLTR(2)

The trace level will be set to 2.