Purpose

Technique SEARCH sets whether the Calibration Data File headers are to be searched when checking file names.

This allows the files for more than one user to be processed.

Valid values are NO (0) and YES (1).

The Global default is NO (0).

This Technique is Universal.

Form of Input

SEARCH(integer)

    where integer is 1 if the Calibration Data File headers are to be
                  searched

Example

SEARCH(1)

    The Calibration Data File headers will be searched.