

NOUS41 KWBC 121848
PNSWSH

Service Change Notice 15-41
National Weather Service Headquarters Washington DC
245 PM EDT Wed Aug 12 2015

To: Subscribers:
 -Family of Services
 -NOAA Weather Wire Service
 -Emergency Managers Weather Information Network
 -NOAAPORT
 Other NWS Partners, Users and Employees

From: Joseph Pica
 Director (Acting), Office of Observations

Subject: Buoy 51100 is no longer supported effective
 immediately; servicing of Buoy 46089 is planned for
 September 2015

Buoy 51100, northeast of Hawaii, is no longer supported effective immediately. Buoy 46089, offshore Tillamook, OR, will now be maintained as part of the NWS weather buoy network. Buoy 46089, 85 nautical miles west northwest of Tillamook, OR, had been funded by the National Ocean Service (NOS) Coastal Storms Program (CSP) until 2013. This buoy had been considered unfunded since then and was to be disestablished this year.

Buoy 51100, 252 nautical miles northeast of Honolulu, HI, is redundant with Buoy 51000, 245 nautical miles northeast of Honolulu.

Buoy 51100 will be moved to the Oregon location to cover the gap associated with the loss of sponsorship and pending disestablishment of Buoy 46089.

For more information on Buoy 46089 and its current data, see the link below.

http://www.ndbc.noaa.gov/station_page.php?station=46089

For questions on the service impacts of this change, contact:

Thomas Trunk
Program Management Branch
Office of Observations
Silver Spring, MD 20910
301-427-9335
Thomas.Trunk@noaa.gov

For technical questions regarding this change, contact:

Shannon McArthur
National Weather Service
Program Manager, NOAA National Data Buoy Center
228-688-2830
shannon.mcarthur@noaa.gov

National Service Change Notices are online at:

<http://www.weather.gov/os/notif.htm>

\$\$