

## Goose Creek near Leesburg, Virginia

Goose Creek near Leesburg, Virginia						
Latitude:	Longitude:	Gauge Elevation:	Drainage Area:	County of Gage:	County of Town:	Weather Office:
39°01'10" or 39.019444° N	77°34'40" or 77.577778° W	248.93 feet	332 mi <sup>2</sup>	Loudoun, VA	Loudoun, VA	Sterling
Major Basin:	Sub Basin:	Minor Sub Basin:		Minor:	Moderate:	Major:
Potomac	Potomac	Potomac		12.00	15.00	18.00
Period of Record (used in flood frequency)			Outside Period of Record (not used in flood frequency)			
6/1/2011 to Present			1909 to 5/31/2011			
Feet	Flood Impacts					
23.00	Highway 15, Evergreen Mills Road, and Lime Kiln Road are all flooded. Tributary flooding strands residents near Oatlands Mill.					
20.00	Highway 15 is flooded south of Leesburg.					
18.00	Water threatens several homes south of Leesburg. Highway 15 will likely have to be closed.					
16.00	Water reaches Highway 15 near the intersection with Oatlands Mill Road.					
15.00	Water approaches a home near Highway 15 south of Leesburg.					
14.00	Water approaches low spots along State Route 733, Lime Kiln Road. Water is in the backyards of homes near Highway 15, and reaches the underside of two low bridges over the creek at Crooked Bridge Lane. Portions of Goose Creek Golf Course are flooded.					
13.00	Water reaches backyards near Highway 15 south of Leesburg. A low spot on State Route 650, Oatlands Road, is flooded.					
12.00	The creek overflows its banks near Oatlands, south of Leesburg. Backwater flooding begins to affect a low spot on State Route 650, Oatlands Road. Water also reaches the Goose Creek Golf Course.					
11.00	The creek reaches bankfull. Some minor overbank flooding is occurring between Middleburg and Oatlands.					
10.00	Water begins to overflow the banks near Evergreen Mill into nearby fields.					
Gauge Stage Changes						
Start and End Date	Minor	Moderate		Major		
Not available	Not available	Not available		Not available		