

## South Branch Potomac River near Springfield, West Virginia

<b>Latitude:</b>	<b>Longitude:</b>	<b>Gauge Elevation:</b>	<b>Drainage Area:</b>	<b>County of Gage:</b>	<b>County of Town:</b>	<b>Weather Office:</b>
39°26'49" or 39.446944° N	78°39'16" or 78.654444° W	561.41 feet	1,461 mi2	Hampshire, WV	Hampshire, WV	Sterling
<b>Major Basin:</b>	<b>Sub Basin:</b>	<b>Minor Sub Basin:</b>		<b>Minor:</b>	<b>Moderate:</b>	<b>Major:</b>
Potomac	South Branch Potomac	South Branch Potomac		15.00	19.00	25.00
<b>Period of Record (used in flood frequency)</b>			<b>Outside Period of Record (not used in flood frequency)</b>			
9/25/1928 to Present			1877 to 9/24/1928			
<b>Feet</b>	<b>Flood Impacts</b>					
25.00	Most camphouses and a large portion of fields in the area are flooded.					
19.00	Camphouses on the right downstream side of the river are flooded.					
17.00	Water approaches camphouses downstream from the gage.					
15.00	Milleson Mill Road (County Route 28/5) and Clarence Taylor Road (Route 3/7) begin to flood. Water covers a significant portion of meadowlands near the river. The boat launch ramp on the upstream right abutment of the bridge also floods.					
11.00	The river begins to overflow the banks in a few low lying areas. Campers should move away from the river.					
5.00	Hazardous conditions for recreation may exist.					
<b>Gauge Stage Changes</b>						
<b>Start and End Date</b>		<b>Minor</b>		<b>Moderate</b>		<b>Major</b>
Not available		Not available		Not available		Not available