

Bush Kill at Shoemakers, Pennsylvania

Latitude:	Longitude:	Gauge Elevation:	Drainage Area:	County of Gauge:	County of Town:	Minor_Mod_Maj:
41°05'17"	75°02'17"	421.13 feet	117 mi2	Monroe, PA	Cambria, PA	6.0_7.0_8.0

Top Five Lowest Stages

Period of Record - 1964 to September 30, 2016

Date	Crest (ft)	Flow (cfs)	Remarks
9/25/1964	missing	2	Low flow
9/18/1996	0.67	missing	none
9/12/1999	0.79	6	Also occurred 8/13/1999 & 9/10 - 11/1999
9/26/2005	0.80	6	Also occurred 9/14 & 23 - 25/2005
9/12/2010	0.84	missing	none

Additional Low Stage Information

Date	Crest (ft)	Flow (cfs)	Remarks
10/3/1998	0.85	missing	Also occurred 10/1 - 2/1998

Additional Remarks

Low water records are somewhat limited. Therefore some low stages could be missing. Our low stage listing includes valid and sometimes questionable stages. In some cases we have a brief list of questionable stages since it was unclear if the readings were due to a gauge malfunction or there wasn't enough data to determine its validity. Low stage (if found) are listed if there hasn't been any low stages in the last 15 years. The USGS sometime tweak their readings so please contact the USGS if you need more information.