

North Branch Rancocas Creek at Pemberton, New Jersey

Latitude:	Longitude:	Gauge Elevation:	Drainage Area:	County of Gage:	County of Town:	Weather Office:
39°58'12" or 39.969444° N	74°41'04" or 74.684444° W	31.19 feet	118 mi ²	Burlington, NJ	Burlington, NJ	Philadelphia
Major Basin:	Sub Basin:	Minor Sub Basin:		Minor:	Moderate:	Major:
Delaware	Delaware	Delaware		2.50	3.50	4.20
Period of Record (used in flood frequency)				Outside Period of Record (not used in flood frequency)		
8/10/1951 to Present				9/22/1938 to 8/9/1951		
Feet	Flood Impacts					
4.20	Homes along Lee Street, Joe Road, and Jill Court take on water. Residents along Old Georges Lane and Rancocas Trail are subject to evacuations. Homes in Eastampton, including the ones on East Mae Avenue, are inundated.					
3.50	Lee Street, Joe Road, and Jill Court in Southampton are subject to evacuations. Old Georges Lane, Rancoacas Trail in the Ewansville section of Southampton are also flooded. The flooding in Eastampton spreads to West Railroad Avenue and East Mae Avenue.					
2.50	Some minor flooding begins in Eastampton along Rustic, Peninsula, and Paducah Roads. Lee Street, Joe Road, and Jill Court in Southampton also begin to flood.					
Gauge Stage Changes						
Start and End Date		Minor	Moderate		Major	
1/1/1938 to 1/31/2003		2.7	3.5		4.2	