

Public Information Statement  
National Weather Service Tampa Bay Ruskin FL  
223 PM EST Mon Nov 5 2018

...NWS DAMAGE SURVEY FOR 11/02/18 TORNADO EVENTS - UPDATE 1...

.Overview...A squall line moved across Florida Friday. West Central and Southwest Florida received straight line winds of 40 to 65 mph and 4 brief EF1 tornadoes.

.Seminole Tornado...

Rating: EF1  
Estimated Peak Wind: 90 mph  
Path Length /statute/: 1.71 miles  
Path Width /maximum/: 75.0 yards  
Fatalities: 0  
Injuries: 1

Start Date: 11/02/2018  
Start Time: 03:13 PM EDT  
Start Location: 1 S Seminole / Pinellas County / FL  
Start Lat/Lon: 27.8327 / -82.7898

End Date: 11/02/2018  
End Time: 03:16 PM EDT  
End Location: 1 ENE Seminole / Pinellas County / FL  
End Lat/Lon: 27.8429 / -82.7644

Survey Summary:  
Damage in two mobile home parks, one condominium roof, and numerous trees and branches down. The media reported one minor injury.

.Trinity Tornado...

Rating: EF1  
Estimated Peak Wind: 90 mph  
Path Length /statute/: 0.28 miles  
Path Width /maximum/: 50.0 yards  
Fatalities: 0  
Injuries: 0

Start Date: 11/02/2018  
Start Time: 03:17 PM EDT  
Start Location: 2 NNE Trinity / Pasco County / FL  
Start Lat/Lon: 28.2065 / -82.6534

End Date: 11/05/2018  
End Time: 03:18 PM EDT  
End Location: 2 NNE Trinity / Pasco County / FL  
End Lat/Lon: 28.2099 / -82.6511

Survey Summary:  
Three homes with damage to roofs and numerous branches and trees down.

.Spring Hill Tornado...

Rating: EF1  
Estimated Peak Wind: 90 mph  
Path Length /statute/: 0.71 miles  
Path Width /maximum/: 100.0 yards  
Fatalities: 0  
Injuries: 0

Start Date: 11/02/2018  
Start Time: 03:22 PM EDT  
Start Location: 2 NNW Spring Hill / Hernando County / FL  
Start Lat/Lon: 28.4683 / -82.566

End Date: 11/02/2018  
End Time: 03:24 PM EDT  
End Location: 2 N Spring Hill / Hernando County / FL  
End Lat/Lon: 28.4749 / -82.557

Survey Summary:  
Roof damage to 17 homes.

.Land O Lakes Tornado...

Rating: EF1  
Estimated Peak Wind: 90 mph  
Path Length /statute/: 1.21 miles  
Path Width /maximum/: 75.0 yards  
Fatalities: 0  
Injuries: 0

Start Date: 11/02/2018  
Start Time: 04:22 PM EDT  
Start Location: 1 S Land O Lakes / Pasco County / FL  
Start Lat/Lon: 28.2087 / -82.4553

End Date: 11/05/2018  
End Time: 04:24 PM EDT  
End Location: 1 E Land O Lakes / Pasco County / FL  
End Lat/Lon: 28.2173 / -82.438

Survey Summary:  
Two homes condemned due to roof damage. Numerous trees and branches down.

EF Scale: The Enhanced Fujita Scale classifies tornadoes into the following categories:

EF0...Weak.....65 to 85 mph  
EF1...Weak.....86 to 110 mph  
EF2...Strong....111 to 135 mph  
EF3...Strong....136 to 165 mph  
EF4...Violent...166 to 200 mph  
EF5...Violent...>200 mph

NOTE:

The information in this statement is preliminary and subject to change pending final review of the events and publication in NWS Storm Data.